



USE COPPER OR ALUMINUM WIRE

230/208-60-3

CHART A	
42WH-3	48VH5-3
Fuse A	40A T.D. / 45A T.D.
Fuse B	30A Standard

ALL FUSES CLASS K5

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.