



USE COPPER OR ALUMINUM WIRE

CHART A		FACTORY WIRING	FIELD WIRING
Fuse A	48WHS v	Low Voltage	-----
Fuse B	60A STANDARD	High Voltage	-----
FUSE C	30A STANDARD		

All fuses Class K5.

- ⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.