


	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

OPT. FIELD INSTALLED
MOTOR SPEED SWITCH

HIGH LOW



230/208-60-1

USE COPPER OR ALUMINUM WIRE

- 1 IF THERE IS AN X1 & X2 TERMINAL ON Q674L1181, JUMPER THEM TOGETHER & CONNECT FROM C TO EITHER ONE.
- 2 FOR 208V OPERATION, MOVE THIS WIRE TO 208V TRANSFORMER TAP.
- 3 OUTDOOR THERMOSTAT # 1 FACTORY SET AT 25 DEGREE.
- 4 OUTDOOR THERMOSTAT # 2 FACTORY SET AT 20 DEGREE.