



⚠ FOR 208 OPERATION MOVE THIS WIRE TO THE 208V TRANSFORMER TAP  
 ⚠ FACTORY SET ON 60 MIN CYCLE, RECONNECT TO 30 FOR 30 MIN CYCLE,  
 RECONNECT TO 90 FOR 90 MIN CYCLE

USE COPPER OR ALUMINUM WIRE

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - - -
High Voltage	—	- - - -

6 PIN CONNECTOR FOR OPTIONAL ELECTRIC HEAT PACKAGE.

# LADDER DIAGRAM

