CONNECTION DIAGRAM

DANGER: ELECTRICAL SHOCK HAZARD,
DISCONNECT POWER BEFORE SERVICING



1 SET HEAT ANTICIPATOR AT .6 A

2 FOR 208V OPERATION MOVE THIS WIRE TO 208V TRANSFORMER TAP

USE COPPER OR ALUMINUM WIRE

3 ADD JUMPER Rc - Rh

	FACTORY WIRING	FIELD WIRING
Low Voltage	———	- - - - -
High Voltage	———	- - - - -

IF ANY OF THE ORIGINAL WIRE AS SUPPLIED WITH THE APPLIANCE MUST BE REPLACED, IT MUST BE REPLACED WITH WIRING MATERIAL HAVING A TEMPERATURE RATING OF AT LEAST 105° C. EXCEPT THE IGNITION CABLE WHICH IS 250° C. HIGH VOLTAGE CABLE.

LADDER DIAGRAM



4085-311 A