



WR Series FUSION-TEC Series

FTS Software Change Log

FTS1000.2.0.0	Status: Active	Release Date: 04/06/2018
Update Includes	This release includes software updates that include the following changes: <ul style="list-style-type: none"> • Changed Modbus addressing to reflect new communication standard • Changed status message structure to include more information of unit status • Added 7 day I/O log export feature • Added time synchronization function to PLC controller • Added unit major component lifetimes • Added minimum position function to economizer operation • Changed Run Test operation and added Run Test information screens for more tech friendly operation • Bug Fix – Fixed EEV Initialization bug so EEV will re-initialize on model number change 	
Know Issues	<ul style="list-style-type: none"> • No Known Issues 	
Software Compatibility	<ul style="list-style-type: none"> • LCS6000.2.1.0 	
Hardware Compatibility	<ul style="list-style-type: none"> • WR36AP • WR58AP 	

Software Status

Active	Current version of software.
Available	Stable version available from website or Bard Technical Service.
Discontinued	Software version no longer supported, recommend updating to the Active version.