



Fused Disconnect Switch

460V 60 Hz 3-Ph

USE COPPER OR ALUMINUM WIRE

- ① Set heat anticipators at .40A
- ② Add jumper Rc to Rh.

Model
24VA1
w/9Kw

Factory Wiring ———
Field Wiring - - - - -