


⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

T872N1036/Q672F1299  
or  
T874N1024/Q674F1261

T872R1164/Q672L1185  
or  
T874R1129/Q674L1181



230/208-60-1

USE COPPER OR ALUMINUM WIRE

CHART A

48W12	70/370
48W15	40/440

Fuse A - 60A Time Delay  
Fuse B - 60A Standard

MODEL  
48W12, 48W15  
HEAT PUMP  
10 KW

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

4014-130 K