



CHART A

	42WH	48WH5
Fuse A	50A TD	60A TD
Fuse B	60A STANDARD	

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

ALL FUSES CLASS K5
 ⚠ If there is an X1 and X2 terminal ⚠ For 208V operation move this wire to 208V transformer tap, and connect from C to either one.

USE COPPER OR ALUMINUM WIRE