



Fuse A - 50A T.D. 42WH
60A T.D. 48WH5
Fuse B - 60A Standard
All fuses class K5

FACTORY WIRING	FIELD WIRING
Low Voltage _____	High Voltage - - - - -
High Voltage _____	Low Voltage - - - - -

MODEL
42WH, 48WH5
HEAT PUMP
20 Kw

⚠ If there is an X1 and X2 terminal ⚠ For 208V operation move this wire to 208V transformer tap. and connect from C to either one.

USE COPPER OR ALUMINUM WIRE

4014-1524