



⚠ If there is an X<sub>1</sub> and X<sub>2</sub> terminal on Q674L1181, jumper them together and connect from C to either one.

MODEL  
48WHZ  
HEAT PUMP  
0 Kw

USE COPPER OR ALUMINUM WIRE

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - -
High Voltage	—	- - -