



USE COPPER OR ALUMINUM WIRE

230/208-60-3

CHART A	
42WH-3	48WH5-3
Fuse A	40A T.D., 45A T.D.
Fuse B	30A Standard

ALL FUSES CLASS K5

FACTORY WIRING **FIELD WIRING**
 Low Voltage ———
 High Voltage - - - -

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

MODEL
 42WH-3, 48WH5-3
 HEAT PUMP
 w/9 KW