



T872N1036/Q672F1299 or T874N1024/Q674F1261
 T872R1164/Q672L1185
 or
 T874R1129/Q674L1181

CHART A

	12MH-3	48MH5-3
Fuse A	40A I.D.	45A I.D.
Fuse B	40A Standard for 12Kw	45A Standard for 15Kw

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

230/208-60-3

ALL FUSES CLASS K5

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

4014-230T