



T872N1036/Q672F1299 or T874N1024/Q674F1261
 T872R1164/Q672L1185
 T874R1128/Q674L1181

CHART A

Fuse A	42WH-3	48WH5-3
Fuse B	40A T.D.	45A T.D
	60A Standard	

FACTORY WIRING FIELD WIRING
 Low Voltage —————
 High Voltage - - - - -

MODEL
 42WH-3, 48WH5-3
 HEAT PUMP
 w/18KW

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

4014-2400

250/208-60-3