



⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

USE COPPER OR ALUMINUM WIRE

MODEL  
48WH2  
HEAT PUMP  
0 Kw

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

Fused Disconnect Switch

460-60-3

4014-3100