



USE COPPER OR ALUMINUM WIRE

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.

⚡ For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage - - - - -	-----

MODEL  
48WH2, 46WH5  
HEAT PUMP  
0 Kw

4014-310K

Fused Disconnect Switch

A60-60-3