



- ⚠ Reroute jumper from X2-W2 to X2-E.
- ⚠ Set heat anticipators at .40A

USE COPPER OR ALUMINUM WIRE

MODEL 48WH1
w/9, 12, 15KW

Factory Wiring ———
Field Wiring - - - -

4014-320C

460V 60Hz 3Ph