



⚠ If there is an X1 and X2 terminal on Q674L1181, ⚠ For 208V operation move this jumper between them together and connect from C to 208V transformer tap.

USE COPPER OR ALUMINUM WIRE	FACTORY WIRING	FIELD WIRING
	Low Voltage	-----
	High Voltage	-----