



USE COPPER OR ALUMINUM WIRE

Fuse A - 45A Time Delay
 Fuse B - 30A Standard

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage _____	Low Voltage _____
High Voltage _____	High Voltage _____

MODEL
 48WH2, 48WH5
 HEAT PUMP
 w/ 6 or 9Kw

230/208-60-3

4014-812 B