



REFER TO INSTALLATION INSTRUCTIONS
FOR CONTROL CIRCUIT WIRING

EQUIPMENT
GROUND

FUSED
DISCONNECT
SWITCH

NEUTRAL

415/380 - 50 - 3

TERMINAL
BLOCK

USE COPPER
CONDUCTORS ONLY

	FACTORY WIRING	FIELD WIRING
Low Voltage	—————	-----
High Voltage	—————	-----



RECONNECT FROM 5-60 TO 5-30
FOR 30 MINUTE CYCLE