



# CONNECTION DIAGRAM

**DANGER: ELECTRICAL SHOCK HAZARD,  
DISCONNECT POWER BEFORE SERVICING.**



# LADDER DIAGRAM



FACTORY WIRING \_\_\_\_\_  
FIELD WIRING - - - - -

IF ANY OF THE ORIGINAL WIRE AS SUPPLIED WITH THE APPLIANCE  
MUST BE REPLACED, IT MUST BE REPLACED WITH WIRING MATERIAL  
HAVING A TEMPERATURE RATING OF AT LEAST 105 C.

ALL MODELS, 1 & 2 SPEED, STANDING PILOT  
WIRING DIAGRAM  
4046-100A