



Use Minimum  
Transformer  
Rating of  
40VA



FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

230/208-60-1

4062-110 A