

G R Y W1 W2


T874C1000 THERMOSTAT
Q674A1001 SUBBASE

Rh G Rc Y W

T87F THERMOSTAT
Q539F SUBBASE
OR
IF56 THERMOSTAT

460-60-3

GROUND



BK - BLACK
BL - BLUE
BR - BROWN
GR - GRAY
G - GREEN
O - ORANGE
PR - PURPLE
R - RED
Y - YELLOW
W - WHITE

USE COPPER OR ALUMINUM WIRE

LOW VOLTAGE
HIGH VOLTAGE

FACTORY WIRING
FIELD WIRING

460-230
STEPDOWN TRANSFORMER
3.0 KVA