



⚠ FOR 208 OPERATION MOVE THIS WIRE TO THE 208V TRANSFORMER TAP  
⚠ FACTORY SET ON 60 MIN CYCLE, RECONNECT TO 30 FOR 30 MIN CYCLE, RECONNECT TO 90 FOR 90 MIN CYCLE

230/208-60-1  
240/208-50-1  
PER NAMEPLATE

USE COPPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 75° C

	FACTORY WIRING	FIELD WIRING
Low Voltage	—	- - - -
High Voltage	—	- - - -

### LADDER DIAGRAM

