



CKT. A
CKT. B
230/208-60-1

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.
⚠ For 208V operation move this wire to 208V transformer tan.

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

MODEL . . .
42WH, 48WH3
HEAT PUMP
5 Kw

4014-121 E