


T872N1036/Q672F1299
or
T874N1024/Q674F1261

T872R1164/Q672L1185
or
T874R1129/Q674L1181



Fuse A - 60A Time Delay
Fuse B - 60A Standard
All fuses class K5.

	FACTORY WIRING	FIELD WIRING
Low Voltage	—————	- - - - -
High Voltage	—————	—————

MODEL
42NH, 48NH5
HEAT PUMP
20 Kw

⚠ If there is an X1 and X2 terminal ⚠ For 208V operation move this wire to 208V transformer tap. and connect from C to either one.

USE COPPER OR ALUMINUM WIRE

4014-150M