



230/208-60-3

CHART A

Fuse A	42NH-3	48NH5-3
Fuse B	40A T.D.	45A T.D.
	40A Standard for 12kw	45A Standard for 15kw

ALL FUSES CLASS R5

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING **FIELD WIRING**
 Low Voltage ————
 High Voltage ————

4014-230 U