



40 AMP. BREAKER (42MI-3)  
45 AMP. BREAKER (48WHIS-3)

40 AMP. Circuit Breaker for 12KW  
50 AMP. Circuit Breaker for 15KW.

CKT. A

CKT. B

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.  
⚠ For 208V operation move this wire to 208V transformer tap.

230/208-60-3

**USE COPPER OR ALUMINUM WIRE**

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

4014-231 G