



T872N1036/Q672F1299 or T874N1024/Q674F1261

T872R1164/Q672L1185
T874R1129/Q674L1181



USE COPPER OR ALUMINUM WIRE

CHART A	
	42NH-3 48NH5-3
Fuse A	40A T.D. 45A T.D.
Fuse B	60A Standard

ALL FUSES CLASS K5

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

⚠ For 208V operation move this wire to 208V transformer tap.

4014-240U

230/208-60-3