


**REVISED DIAGRAM
REPLACES
4014-3106
DATE 8-16-82**

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

MODEL
48WH2, 48WH4
HEAT PUMP
0 Kw

FACTORY WIRING FIELD WIRING
Low Voltage ———
High Voltage - - - -



USE COPPER OR ALUMINUM WIRE