



Fused Disconnect Switch

USE COPPER OR ALUMINUM WIRE

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

MODEL
48WH2, 48WH5
HEAT PUMP
9, 12, 15 Kw

460-60-3

4014-320 K