


▲ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.

▲ For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage ———	—————
High Voltage - - - -	- - - -

MODEL  
48WH2, 48WH5  
HEAT PUMP  
9, 12, 15 Kw



USE COPPER OR ALUMINUM WIRE