


T872N1036/Q672F1299  
 or  
 T874N1024/Q674F1261

T872R1164/Q672L1185  
 or  
 T874R1129/Q674L1181



**USE COPPER OR ALUMINUM WIRE**

| CHART A |                  |
|---------|------------------|
| Fuse A  | 50A T.D. 48WH5 v |
| Fuse B  | 60A STANDARD     |
| FUSE C  | 30A STANDARD     |

| FACTORY WIRING | FIELD WIRING |
|----------------|--------------|
| Low Voltage    | -----        |
| High Voltage   | -----        |

All fuses Class K5.

- ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.