


T872N1036/0672F1299 or T874N1024/0674F1261

T872R1164/0672L1185  
T874R1129/0674L1181



USE COPPER OR ALUMINUM WIRE

Fuse A - 45A Time Delay  
Fuse B - 30A Standard

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

MODEL  
48WH2, 48WH5  
HEAT PUMP  
w/6 or 9Kw

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

230/208-60-3

4014-808 B