



	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	- - - - -
High Voltage	—————	- - - - -

CHART A	
UNIT SIZE	CAP. SIZE
3 1/2 TON	40/440
4 TON	70/370
5 TON	45/440