


REFER TO INSTALLATION INSTRUCTIONS  
FOR CONTROL CIRCUIT WIRING.



24V TERMINAL STRIP

C R Y Y1 B W1 DH L W3 O1

COMPRESSOR

IMMERSION  
CRANKCASE  
HEATER

15/440  
CAPACITOR

OUTDOOR FAN

COMPRESSOR  
CONTACTOR

10/370  
CAPACITOR

REV. VALVE ( 24V )

HI-PRESSURE  
SWITCH

DEFROST  
RELAY

DEFROST  
THERMOSTAT

TIMER  
( 7 MIN. TIME-SAFE )

EQUIPMENT  
GROUND

FUSIBLE  
DISCONNECT  
SWITCH

USE COPPER  
CONDUCTORS ONLY

	FACTORY WIRING	FIELD WIRING
Low Voltage	—————	- - - - -
High Voltage	—————	- - - - -

220/200 - 50 - 1