



T874C1000 THERMOSTAT
 Q674A1001 SUBBASE

T87F/0539 OR 1F56
 THERMOSTAT

- △1 NOT REQUIRED WHEN OPTIONAL HEAT PACKAGES ARE NOT INSTALLED
- △2 REQUIRED ONLY FOR USE WITH OPTIONAL ELECTRIC HEAT PACKAGES: EH3PA-A15, EH3PA-B12, EH3PA-B15, WHEN TWO STAGE HEAT IS DESIRED.
- △3 FOR 208V OPERATION MOVE THIS WIRE TO 208V TRANSFORMER TAP.

	FACTORY WIRING	FIELD WIRING
LOW VOLTAGE	_____	-----
HIGH VOLTAGE	—————	-----

USE COPPER OR ALUMINUM WIRE

FUSED DISCONNECT SWITCH

230/208V 60HZ 3-PH
 220/200V 50HZ 3-PH