REPLACEMENT PARTS MANUAL

Wall-Mounted Gas/Electric Commercial Room Ventilator with Exhaust

Models:

WGCRVS-3C WGCRVS-5C

General Notes

- Revised and/or additional pages may be issued from time to time
- ➤ A complete and current manual consists of pages shown in the following contents section.

Important


Contact the installing and/or local Bard distributor for all parts requirements. Be sure to have the complete model and serial number available from the unit rating plates.

Contents

Description	Page
Cabinet Components Exploded View Usage List	
Functional Components • Exploded View • Usage List	
Actuator Replacement Parts Reference Guide	4



Bard Manufacturing Company, Inc. Bryan, Ohio 43506 www.bardhvac.com Manual: 2110-1141A Supersedes: 2110-1141 Date: 8-10-22



Mist Eliminator

Fill Plate Assembly with Screen

Fill Plate Assembly with Screen

Bottom Fill

Bottom Fill

Χ

Χ

Χ

Χ

Χ

NS = Not Shown

9

NS

NS

NS

NS

7003-054


136-459

136-465

542-134

542-139

Manual 2110-1141A Page 2 of 4



SEXP-360 B

			/S-3C	/S-5C
Drawing No.	Part No.	Description	WGCRVS-3C	WGCRVS-50
1	8602-052	Bushing	2	2
2	8602-038	Damper Blade Pin	2	2
3	8602-040	Bracket	X	Χ
4	See page 4	Damper Motor	X	Х
5	3000-1712	Wire Assembly	X	Χ
6	8602-008	Ball Joint	Х	Х
7 7	8602-044 8602-047	Rod Rod	Х	Х
8	8201-130	Relay	X	Х
9	113-907	CRV Control Board Bracket	Х	Х
10	8201-167	CRV Control Board	Х	Х
NS	3000-1715	Wire Harness - Damper to Unit	Х	Х

NS = Not Shown


ACTUATOR REPLACEMENT PARTS REFERENCE GUIDE

Belimo Actuator

If the V option CRV was produced after 8/10/22, it will most likely have a Belimo actuator assembly (see image). These include the vent models and assembly numbers listed in the table. Use replacement part numbers listed in table.

Vent Model	Assembly	Actuator Bracket	Actuator Motor & Hardware	Entire Actuator Assembly
WGCRVS-3C	920-0565	113-962	8602-117	910-2230
WGCRVS-5C	920-0566	113-962	8602-117	910-2230
WGSCRVMP-5A	920-0570	113-962	8602-117	910-2230

Belimo Actuator Assembly




Honeywell Diamond Actuator

If the V option CRV was produced between 12/31/21 and 8/10/22, it will most likely have a Honeywell Diamond actuator assembly (see image). These include the vent models and assembly numbers listed in the table. Please use the new Belimo 910- assemblies listed as drop-in replacement for the Diamond actuator or any associated parts.

Vent Model	Assembly	Entire Actuator Assembly (Use to replace 910-2187, 8602-114 or 8602-115)	
WGCRVS-3C	920-0533	910-2230	
WGCRVS-5C	920-0532	910-2230	
WGSCRVMP-5A	920-0537	910-2230	

Honeywell Diamond Actuator Assembly (Obsolete)




Honeywell Black Box Actuator

If the V option vent was produced before 12/31/21, it will most likely have one of the Honeywell Black Box actuator models listed in the table. Use replacement motors from service stock until depleted. If stock is depleted, use the associated replacement kit number in table.

Vent Model	Assembly	Bard Part #	Honeywell Black Box Part #	Actuator Replacement Kit
WGCRVS-3B	920-0060	8602-020	M8405A1006	8620-353
WGCRVS-5B	920-0058	8602-020	M8405A1006	8620-353
WGSCRVMP-5	920-0042	8602-037	M7415A1004	8620-354

Honeywell Black Box Actuator Assembly (Obsolete)



MIS-4389